

STOCK SAW WARM-UP



STOCK SAW WARM-UP



REQUIREMENTS

- Number of Stock Saws
 - Minimum requirements
 - 3x MS661 C-M
 - 2 competition saws and 1 backup saw
- Recommendation of STIHL
 - 4x MS661 C-M
 - 2 competition saws and 2 backup saws
- Block of wood with minimum 400mm diameter
 - Needed for the Stock Saw warm-up

STOCK SAW WARM-UP



AUTOMATIC ADJUSTMENT BEFORE COMPETITION START

Carry out **five uniform cuts** to length under full load with each Stock Saw, **1 day before the competition start.**

The cuts must be with the same feed force.

STOCK SAW WARM-UP




WARM-UP PROCESS

- The warmup process must be started maximum **five minutes before the competition start.**
- Block of wood with minimum 400mm diameter is needed for the warm-up process
- Carry out 4 uniform cuts to length with each Stock Saw
 - The cuts must be sawn with the same feed force and in the rpm range 8000 to 11000 RMP.
- Check the chain tension after the warm-up process

STOCK SAW WARM-UP

PROVIDING THE STOCK SAW

- Provide the saw to the athlete in the **I** position
- If the Stock Saw do not start after two start attempts, move the master control lever in the ▲ position and try to start the engine again



STOCK SAW WARM-UP



WARM-UP PROCESS OF THE BACKUP SAW

- Warm-up the backup saw during a wood block change again
- Carry out 2 uniform cuts to length with the backup saw again
- Check the chain tension after the warm-up process



STIHL
TIMBERSPORTS[®]
— THE ORIGINAL EXTREME SPORT —

